Weather zation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 10001BL0459
Work Order Type: Weatherization

CLIENT INFORMATION

Client Name: Address:

Client ID: 10001BL0459 , 37737

Alt. Client ID: BLOUNT

AGENCY INFORMATION

Agency: Blount County Community Action Agency Agency Phone: (865) 983-8411

Address: 3509 Tuckalee Pike **Fax:** (865) 681-1781

Maryville, TN 37803 *Email Address:*

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Auditor: Bruce Larson (865-310-7333)

Audit conducted on 3/26/2012

1997 Mobile Home

	stall 150 sq. ft. R-19 Fibe sulation & 150 Sq. ft. Bel	_	tt	Componen	ts			Inspected
mobile have to	150 sq. ft. R-19 Fiberglas home floor. (this amoun be be remove prior to instal ed on East Wall, Under Ma	nt of old/tor llation of ne	n/hang					
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Comment Remove of mob	move approx. 150 sq. ft. n/hanging Insulation & I ve approx. 150 sq. ft. of to bile home. ed on East Wall, Under Ma	Belly Wrap orn/hanging		Componen		om floor	,	Inspected
Comment Remove of mob	n/hanging Insulation & I ve approx. 150 sq. ft. of to bile home.	Belly Wrap orn/hanging		•	Wrap fro	om floor	Actual	Inspected
Comment Remove of mob	n/hanging Insulation & I ve approx. 150 sq. ft. of to bile home.	Belly Wrap orn/hanging		ation & Belly	Wrap fro	om floor		Inspected
Comment Remove of mobility Locate	n/hanging Insulation & I ve approx. 150 sq. ft. of to pile home. ed on East Wall, Under Ma	Belly Wrap orn/hanging aster Bath.	ı Insula	ation & Belly Estimated	Wrap fro		Actual	
Comment Remove of mobility Locate # Material / Labor	n/hanging Insulation & I we approx. 150 sq. ft. of to pile home. ed on East Wall, Under Ma Description / Comment	Belly Wrap orn/hanging aster Bath. <i>Unit</i> s	Insula Qty	ation & Belly Estimated	Wrap fro		Actual	
tor Comment Remove of mobility Locate # Material / Labor 10 Unspecified	n/hanging Insulation & I we approx. 150 sq. ft. of to pile home. ed on East Wall, Under Ma Description / Comment	Belly Wrap orn/hanging aster Bath. <i>Unit</i> s	Insula Qty	ation & Belly Estimated	Wrap fro		Actual	
tor Comment Remove of mobility Locate # Material / Labor 10 Unspecified	n/hanging Insulation & I we approx. 150 sq. ft. of to pile home. ed on East Wall, Under Ma Description / Comment	Belly Wrap orn/hanging aster Bath. <i>Unit</i> s	Insula Qty	ation & Belly Estimated	Wrap fro		Actual	
tor Comment Remove of mobility Locate # Material / Labor 10 Unspecified	n/hanging Insulation & I we approx. 150 sq. ft. of to pile home. ed on East Wall, Under Ma Description / Comment	Belly Wrap orn/hanging aster Bath. <i>Units</i> Each	Qty 1	ation & Belly Estimated	Wrap fro	Qty	Actual	
tor Comment Remove of mobility Locate # Material / Labor 10 Unspecified	n/hanging Insulation & I we approx. 150 sq. ft. of to pile home. ed on East Wall, Under Ma Description / Comment	Belly Wrap orn/hanging aster Bath. <i>Units</i> Each	Qty 1	Estimated Unit Cost	Wrap fro	Qty	Actual Unit Cost	
tor Comment Remove of mobility Locate # Material / Labor 10 Unspecified Other Detail	n/hanging Insulation & I we approx. 150 sq. ft. of to pile home. ed on East Wall, Under Ma Description / Comment	Belly Wrap orn/hanging aster Bath. <i>Units</i> Each	Qty 1	Estimated Unit Cost	Wrap fro	Qty	Actual Unit Cost	
tor Comment Remove of mobility Locate # Material / Labor 10 Unspecified Other Detail	n/hanging Insulation & I we approx. 150 sq. ft. of to pile home. ed on East Wall, Under Ma Description / Comment	Belly Wrap orn/hanging aster Bath. <i>Units</i> Each	Qty 1	Estimated Unit Cost	Wrap fro	Qty	Actual Unit Cost	

1	Measure 3	Rem Bath	ove/Replace Duct Boot	t in Maste	er	Compone	nts		1	Inspected
C	omment Re	move	/Replace Duct Boot in M	aster Bat	h					
	Thi	is nee	ds to be done prior to in	nstalling Ir	nsulatio	n/Belly Wra	-		Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified		Misc Material	Each	1					
0	ther Detail							, ,		
L										
]		
					Measur	e Sub Total:		,	Sub Total:	
	Fib 2.	Insula erglas Foam	eral Air Sealing ate Around Garden Tub. as batting. Approx. 5 LN a Kitchen drain lines a Hall & Master Bath drai	N FT.		Compone available. Fo		tall	1	Inspected
	J.	ruan	i i idii & iviastei batti urai	111 111165		Estimate	d		Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation		General air sealing (setup cost)	Each	1					
10	Miscellaneou	ıs Su	Infiltration Reduction	Each	1					
0	ther Detail									
] [
					Measur	e Sub Total:		,	Sub Total:	
	Field Notes:									

	/H Pipe Insulation e 5' Water Pipes each (H	ot/Cold)		Componen	its			Inspected
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Pipe Insulation	Each	1					
2 Labor	DWH Pipe Insulation	Each	1					
Other Detail						7 [
][] []		
			Measur	e Sub Total:] ;	Sub Total:	
Measure 6 DW Comment 30 Gall	/H Tank Insulation			Componen	nts			Inspected
Common to Can				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Tank Insulation	Each	1					
2 Labor	DWH Tank Insulation	Each	1					
Other Detail	7					¬ [
] []] []		
			Measur	e Sub Total:		_	Sub Total:	
Field Notes:				L				
		Work O	rder Gra	and Total:		Gran	d Total:	